



3342 Blue Star Highway Saugatuck, MI 49453 269 857-3000 / Fax: 269 857-1228 E-mail: info@saugatuckfire.org

FIRE DISTRICT "SPECIAL" BOARD MEETING

4:00pm – January 31st, 2022 **AGENDA**

- 1. Call to Order:
- 2. Pledge of Allegiance (Stand if you are able):
- 3. Roll Call:
- 4. Reminder: It is requested that the board silences cell phones and put them away for the duration of the meeting.
- 5. Approval of Agenda (additions / deletions):
- 6. Public Comment on Agenda Items Only (Limit 3 minutes):
- 7. Unfinished Business: A. None
- 8. New Business:
 A. Funding Approval Request Engine #2112 (2011 KME) Emergency Engine Repair
- 9. Public Comments: (Limit 3 minutes):
- 10. Fire Board Comments:
- 11. Adjournment:

NOTICE

Request for accommodations or interpretive services must be made 48 hours prior to this meeting. Please contact Saugatuck Township Fire District at 269-857-3000 for further information.



3342 Blue Star Highway Saugatuck, MI 49453 269 857-3000 / Fax: 269 857-1228 E-mail: <u>info@saugatuckfire.org</u>

January 28th, 2022

Funding Approval Form

ITEM DESCRIPTION:

Engine #2112 – (2011 International/KME) – Emergency Engine Repair

PRIORITY:

EMERGENCY

QUALITY FACTORS:

Engine 2112 began experiencing trouble on 1/12/2022 and has been out of service since with no acceleration when put in gear. We contacted K&R Truck Sales, the International Dealer for West MI. After inspecting onsite, they determined there is something further wrong with the turbos and exhaust gas recirculating valve/cooler.

We took the truck to their shop for further diagnosis, and Chief Janik authorized up to \$3,200 in diagnostic time to determine the issue. After the teardown is completed, we received the updated estimate on 1/28/22 for \$26,258.37 which includes the previously approved diagnostic time. The Engine needs the exhaust brake, one turbo, the EGR valve, EGR cooler, and several other tubes/clamps to put it all together. Unfortunately, this is apparently a common issue with the MaxxForce diesel engines in International trucks of that era due to all of the emissions requirements. K&R Estimates the repairs should be complete by about February 11th, 2022.

BUDGETED:

Unbudgeted Expense – 2021/22 Fiscal Year

FUNDING SOURCE(S): Fund Balance – 2021/22 Fiscal Year - \$26,258.37

<u>COST:</u> Repair Estimate from K&R – \$26,258.37 <u>Contingency- \$3,741.63</u>

Total = \$30,000.00

<u>REQUESTER:</u> Deputy Chief Chris Mantels

SAMPLE MOTION:

I_____ motion to authorize Fire District staff to coordinate engine repairs with K & R Truck Sales for Engine #2112 with a not to exceed amount of \$30,000.00. I_____ 2nd the Motion. (Roll Call Vote)





840 INTERCHANGE DRIVE HOLLAND, MI 49423 P: (616) 392-8377 F: (616) 392-6755 Facility Lic F142376

BILL TO SAUGATUCK TWP FIRE DEPARTMENT - 14804 3342 BLUE STAR HWY SAUGATUCK MI 49453 P: (269) 857-3000 F:

DELIVER TO

SAUGATUCK TWP FIRE DEPARTMENT - 14804 3342 BLUE STAR HWY SAUGATUCK MI 49453 P: (269) 857-3000 F:

SERVICE ESTIMATE: E201003702

DAT	TE ARRIVED		DATE INVOICE	SALES TYPE		ADVISOR		TERMS	CUSTOMER R	EFERENCE
/18/2022	4:26:01PI	M		SRET		Kristina Ellens		CASH		
YEAR	MAKE		MODEL	VIN	Unit ID	CUST UNIT # E	INGINE HOURS	IN SERVICE Com	ponent Serial #	ODOMETER
2011	INTERNAT	IONAL	7000 SERIES	1HTWMAZRXBJ386870	105277	2112	0	12/31/9999		0
				Estimate	e Operati	ons				
JOB #1	12	ENGIN	NE							
COMPLA CAUSE CORREC		TEAR D	OWN							
QTY	ITEM			DESCRIPTION				UNIT	PRICE	EXTD PR
20.00	LABOR 1	2-10		TEAR DOWN						2,850.
	1				Prepa	y: 0.00 Parts: \$0	Labor: \$2,850	0.00 Misc: \$0 Sub	let: \$0	\$2,850.0
COMPLA CAUSE CORREC		CUSTON 401-CHI AFTER STANDA MOVE,	MER COMPLAI ECKED CODES DRIVE IT WOU ARD AND AIR M DURING AIR M	MAL HOURS (7AM-5PM NED THAT TRUCK HAS ONLY CODES PRESEN LD NOT IDLE CORREC MANAGEMENT TEST. E IANAGEMENT TEST IT ERE DONE ON LAPTOP	S NO POW T WERE TLY. RES OURING S WOULD	VER WHEN SHI FOR SOOT LOA TARTED AND I TANDARD TES	AD, RAN A R T CLEAREI ST EXHAUS	EGEN, AND TES D UP. PERFORMI T BRAKE WOUL	ED .D NOT	
QTY	ITEM			DESCRIPTION				UNIT	PRICE	EXTD PR
22	MILEAG			SERVICE TRUCK M	IILEAGE	@ \$1.75 PER M	ILE		1.75	38.
2.70) LABOR S	C1		SERVICE CALL - NO	ORMAL F	IOURS (7AM-5I	PM MON-FR	I)		391.
					Prepay	: 0.00 Parts: \$0]	Labor: \$391.50) Misc: \$38.50 Sub	let: \$0	\$430.0



		Estimate Operations (Cont.)						
JOB #3 12	ENGINE							
COMPLAINT CAUSE								
CORRECTION	273 - I PULLED A HEALTH REPORT. HAS NO FAULT CODES. ENGINE RUNS ROUGH. RAN AMT AND EGR							
		ETS. I DROVE FOR LESS THEN A MILE AND I GOT A DPF PLU						
	LEVEL FAULT CODE AND THE EXHAUST TEMP WAS ALREADY OVER 850 DEGREES AT THAT TIME.							
	RECOMEND REMOVING THE DPF AND DOC FOR CLEANING AND CHECKING THE DPFDP TUBES FOR BLUGGING, ALSO NEED TO DO A SNAP THROTTLE TEST WITH THE AFTERTREATMENT DISCONNECTED							
	PLUGGING. ALSO NEED TO DO A SNAP THROTTLE TEST WITH THE AFTERTREATMENT DISCONNECTED TO CHECK FOR EXCESSIVE BLACK SMOKE I FOUND THE EXHAUST BACK PRESSURE VALVE							
	TO CHECK FOR EXCESSIVE BLACK SMOKE. I FOUND THE EXHAUST BACK PRESSURE VALVE INTERMITENTLY STICKS PARTIALLY CLOSED. RECOMEND REPLACING THE EXHAUST BACK PRESSURE							
	VALVE. ALSO RECOMEND REPLACING THE AFTERTREATMENT FUEL DOSER AS THERE IS AN UPDATED							
	STYLE. I RAN THE EGR VALVE TEST AND IT DID NOT SET A FAULT CODE. NEED TO REMOVE THE INTAKE							
	THROTTLE VALVE AND INSPECT THE EGR MIXING DUCT FOR PLUGGING. IF IT IS PLUGGED THEN WE							
	NEED TO DISSASEMBLE THAT AND CLEAN IT AND THEN REASEMBLE AND RETEST FOR EGR CODES. IF IT							
	IS NOT PLUGGED THEN WE WOULD NEED TO REPLACE THE EGR COOLER. THIS BUILDS LOW BOOST AT							
		HIGH IDLE NO LOAD. RECOMEND CHECKING INTAKE MANIFOLD PRESSURE SENSOR AND EXHAUST BACK PRESSURE SENSOR AND TUBE FOR PLUGGING. THIS STILL HAS THE ONLD STYLE CRANKCASE						
		TS BACK INTO THE INTAKE. RECOMEND UPDATING TO THIS						
		. THIS TYPICALLY REQUIRES THE VALVE COVER TO BE REF						
		VALVE COVER FOR A BAFFLE. THIS DOES HAVE OIL IN THE						
	DETERMINE WHERE	THE OIL IS COMING FROM. IT COULD BE FROM THE TURBO	S OR THE CRANKCASE					
	BREATHER. ALSO NE	ED TO CHECK FOR INTAKE AIR SYSTEM LEAKS.	· · · · · · · · · · · · · · · · · · ·					
		DESCRIPTION	UNIT PRICE	EXTD PRI				
QTY ITEM	D 12 10	ENGDIE / DIGDECT	1	570 (
4.00 LABC		ENGINE / INSPECT		570.0				
4.00 LABO 273 - S	Swain, Brian - M265207		10.00					
4.00 LABC 273 - S		ENGINE / INSPECT CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00	19.00 Misc: \$0 Sublet: \$0	19.0				
4.00 LABC 273 - S 1 201D/ OB #4 12 COMPLAINT CAUSE	Swain, Brian - M265207	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00		570.(
4.00 LABC 273 - S 1 201D/ OB #4 12 COMPLAINT CAUSE CORRECTION	Swain, Brian - M265207 /ZST422154 ENGINE	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T	Misc: \$0 Sublet: \$0	19.0 \$589.0				
4.00 LABC 273 - S 1 1 201D/ OB #4 12 COMPLAINT 2000000000000000000000000000000000000	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION		19.0 \$589.0 EXTD PR				
4.00 LABC 273 - S 2 1 201D/ OB #4 12 OMPLAINT AUSE ORRECTION QTY QTY ITEM 0.00 LABC	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT	UNIT PRICE	19. \$589.0 EXTD PR 0.0				
4.00 LABC 273 - S 2 1 201D/ OB #4 12 COMPLAINT CORRECTION QTY ITEM 0.00 LABC 2 201N/	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10 /2593754C91	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT SENSOR EXH GAS TEMP T1	UNIT PRICE	19. \$589.(
4.00 LABC 273 - S 1 201D/ OB #4 12 COMPLAINT CAUSE CORRECTION QTY ITEM 0.00 LABC 2 201N/ 1 201N/	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10 /2593754C91 /2593756C91	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT SENSOR EXH GAS TEMP T1 SENSOR EXH GAS TEMP LT GRAY T2	UNIT PRICE 202.22 167.14	19. \$589.0 EXTD PR 0.0 404. 167.				
4.00 LABC 273 - 5 1 201D/ OB #4 12 COMPLAINT AUSE CORRECTION QTY ITEM 0.00 LABC 2 201N/ 1 201N/ 2 201N/	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10 /2593754C91 /2593756C91 /2594128C1	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT SENSOR EXH GAS TEMP T1 SENSOR EXH GAS TEMP LT GRAY T2 CLAMP V-BAND	UNIT PRICE 202.22 167.14 124.18	19. \$589.0 EXTD PR 0.1 404.4 167. 248.				
4.00 LABC 273 - S 2 1 201D/ OB #4 12 COMPLAINT COMPLAINT COMPLAINT CORRECTION QTY ITEM 0.00 LABC 2 201N/ 1 201N/ 2 201N/ 2 201N/ 2 201N/	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10 /2593754C91 /2593756C91	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT SENSOR EXH GAS TEMP T1 SENSOR EXH GAS TEMP LT GRAY T2 CLAMP V-BAND GASKET V-BAND FLANGE	UNIT PRICE 202.22 167.14	19. \$589.0 EXTD PR 0.0 404. 167.				
4.00 LABC 273 - S 2 1 201D/ OB #4 12 COMPLAINT 2 CORRECTION 2 QTY ITEM 0.00 LABC 2 201N/ 1 201N/ 2 201N/ 1 201N/ 1 201N/ 1 201N/	Swain, Brian - M265207 /ZST422154 ENGINE REMOVE DPF INSPEC DR 12-10 /2593754C91 /2593756C91 /2594128C1 /2594129C1	CABLE CROSS-OVER STUD TOP 1 Prepay: 0.00 Parts: \$19.00 Labor: \$570.00 T DESCRIPTION ENGINE / INSPECT SENSOR EXH GAS TEMP T1 SENSOR EXH GAS TEMP LT GRAY T2 CLAMP V-BAND	UNIT PRICE 202.22 167.14 124.18 27.51	19.0 \$589.0 EXTD PR 0.0 404.4 167. 248.3 55.0				



S ARE NEEI	PARTS - IF PARTS	Estimate Operations (Cont.)			
		ANDARD BAKE PROGRAM 1 (DO NOT SELL ANY 1	C2 DOC STAGE 2 - S	IOB #5	
	DOC STAGE 2 - STANDARD BAKE PROGRAM 1 (DO NOT SELL ANY PARTS - IF PARTS ARE NEEDED OR LABOR TO R&R CREATE ANOTHER OPERATION)				
				CAUSE CORREC	
EXTD PI	UNIT PRICE	DESCRIPTION		QTY	
10	10.00	DISPOSAL/ENV FEE		1	
200		DOC STAGE 2 - STANDARD BAKE PROGRAM 1	DR DOC2	1.0	
	0.00	***DO NOT SELL ANY PARTS - IF PARTS ARE NEEDED C	ΓS		
\$210.		Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi			
	ARE NEEDED OR	ARD BAKE PROGRAM 1 (DO NOT SELL ANY PARTS - IF PARTS TE ANOTHER OPERATION)		COMPLA CAUSE	
EXTD PI	UNIT PRICE	DESCRIPTION		QTY	
10	10.00	DISPOSAL/ENV FEE		1	
		DPF STAGE 2 - STANDARD BAKE PROGRAM 1	DR DPF2	1.0	
200					
\$210.	0.00 sc: \$10.00 Sublet: \$0	***DO NOT SELL ANY PARTS - IF PARTS ARE NEEDED C Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi	°S	IOB #7	
			S ENGINE REPLACE EXHAUST	JOB #7 COMPLA	
		Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi	S ENGINE REPLACE EXHAUST	COMPLA	
\$210. EXTD PI		Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T	COMPLA CAUSE CORREC	
\$210. \$210. EXTD PI 4,275	sc: \$10.00 Sublet: \$0	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T DR 12-10	COMPLA CAUSE CORREC QTY 30.0	
\$210. \$210. EXTD PI 4,275 82	UNIT PRICE 82.67	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP	ENGINE REPLACE EXHAUST THE 30 HOURS ON T DR 12-10 1846480C2	COMPLA CAUSE CORREC QTY 30.0 1	
\$210. \$210. EXTD PI 4,275 82 138	UNIT PRICE 82.67 69.24	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR	ENGINE REPLACE EXHAUST THE 30 HOURS ON T DR 12-10 1846480C2 1893794C1	COMPLA CAUSE CORREC aty 30.0 1 2	
\$210. \$210. EXTD PI 4,275 82 138 82	UNIT PRICE 82.67 69.24 41.17	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T 0R 12-10 1846480C2 1893794C1 2015983C1	COMPLA CAUSE CORREC 30.0 1 2 2	
\$210. \$210. EXTD PI 4,275 82 138 82 539	UNIT PRICE 82.67 69.24 41.17 539.64	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE INJECTOR,KIT, HC INJECTOR W/GA	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T 08 12-10 1846480C2 1893794C1 2015983C1 2512884C91	COMPLA CAUSE CORREC QTY 30.0 1 2 2 1	
\$210. \$210. EXTD PI 4,275 82 138 82 539 165	UNIT PRICE UNIT PRICE 82.67 69.24 41.17 539.64 165.02	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE INJECTOR,KIT, HC INJECTOR W/GA TUBE ASSY INJECTOR COOLER INLT	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T 71846480C2 71893794C1 2015983C1 2512884C91 7078617C1	OMPL4 AUSE ORREC 0RREC 30.0 1 2 2 1 1 1	
\$210. \$210. EXTD PI 4,275 82 138 82 539 165 198	UNIT PRICE 82.67 69.24 41.17 539.64 165.02 198.15	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE INJECTOR,KIT, HC INJECTOR W/GA TUBE ASSY INJECTOR COOLER INLT TUBE ASSY INJECTOR COOLER OUTL	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T THE 30 HOURS ON T 1846480C2 1893794C1 2015983C1 2512884C91 7078617C1 7078618C1	OMPL/ AUSE ORREC 30.0 1 2 2 1 1 1 1	
\$210. \$210. EXTD PI 4,275 82 138 82 539 165 198 1,173	UNIT PRICE 82.67 69.24 41.17 539.64 165.02 198.15 1,173.55	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE INJECTOR,KIT, HC INJECTOR W/GA TUBE ASSY INJECTOR COOLER INLT TUBE ASSY INJECTOR COOLER OUTL VALVE,BRAKE, ASSY EXH UNDER RA	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T THE 30 HOURS ON T 1846480C2 1893794C1 2015983C1 2512884C91 7078617C1 7078617C1 7078618C1 7095681C92	COMPLA CAUSE CORREC 2000 1 2 2 1 1 1 1 1 1 1	
\$210. \$210. EXTD PI 4,275 82 138 82 539 165 198	UNIT PRICE 82.67 69.24 41.17 539.64 165.02 198.15	Prepay: 0.00 Parts: \$0 Labor: \$200.00 Mi ACK PRESSURE VALVE & SENSOR IS LABOR LINE IS ALSO FOR THE REPAIR LINES BELOW DESCRIPTION ENGINE / INSPECT SENSOR EBP CLAMP EXHAUST PIPE CLAMP TUR GASKET EXH PIPE FLANGE INJECTOR,KIT, HC INJECTOR W/GA TUBE ASSY INJECTOR COOLER INLT TUBE ASSY INJECTOR COOLER OUTL	S ENGINE REPLACE EXHAUST THE 30 HOURS ON T THE 30 HOURS ON T 1846480C2 1893794C1 2015983C1 2512884C91 7078617C1 7078618C1	COMPL/ CAUSE CORREC 30.0 1 2 2 1 1 1 1	



Estimate Operations (Cont.)							
OB #8	12 ENGINE						
OMPLA	INT REPLACE THE EGI						
AUSE	INT KEPLACE THE EOI	(VALVE					
ORREC	TION						
QTY	ІТЕМ	DESCRIPTION	UNIT PRICE	EXTD PRI			
	LABOR 12-10	ENGINE / INSPECT	UNIT PRICE	0.0			
1	201N/1838248C1	GASKET INTAKE THROTTLE	29.06	29.0			
1	201N/1846481C92	SENSOR, PRESSURE ASM	86.15	86.3			
3	201N/1847988C1	SEAL EGR VALVE	23.74	71.2			
1	201N/1884925C1	GASKET INLET DUCT-INTAKE MANIF	24.94	24.9			
1	201N/1890997C92	VALVE ASSEMBLY, EGR	1,101.84	1,101.8			
1	2011(10)0))(0)2	Prepay: 0.00 Parts: \$1,313.21 Labor: \$0	,	\$1,313.2			
OMPLA AUSE ORREC		CONVERSION					
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PR			
0.00	LABOR 12-10	ENGINE / INSPECT		0.0			
2	201N/1823644C1	RING O	0.25	0.			
1	201N/1855127C1	RING O SIZE 214	8.17	8.			
1	201N/1885394C1	HARNESS ASSY ENG BOOST CONTROL	34.26	34.2			
2	201N/1890328C1	SEAL CROSSOVER TUBE	108.93	217.8			
1	201N/2512559C91	BREATHER,KIT, OPEN BREATHER CO	1,502.05	1,502.0			
	1	Prepay: 0.00 Parts: \$1,762.84 Labor: \$0	Misc: \$0 Sublet: \$0	\$1,762.8			
) 12 ENGINE						
OB #10 OMPLA AUSE ORREC		ESSURE TURBO					
OMPLA AUSE ORREC ⁷ _{QTY}	TION	DESCRIPTION	UNIT PRICE	EXTD PR			
OMPLA AUSE ORREC ^T QTY 0.00	ITEM LABOR 12-10	DESCRIPTION ENGINE / INSPECT		0.			
OMPLA AUSE ORREC ⁷ QTY 0.00 12	TION ITEM LABOR 12-10 201N/1841574C2	DESCRIPTION ENGINE / INSPECT NUT FLANGE M10 X 1.25 SPL THD	20.55	0. 246.			
OMPLA AUSE ORRECT QTY 0.00 12 4	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1	DESCRIPTION ENGINE / INSPECT NUT FLANGE M10 X 1.25 SPL THD STUD M10 X 75MM	20.55 21.92	0. 246. 87.			
OMPLA AUSE ORRECT QTY 0.00 12 4 3	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1	DESCRIPTION ENGINE / INSPECT NUT FLANGE M10 X 1.25 SPL THD STUD M10 X 75MM STUD M10 X 39MM	20.55 21.92 12.83	0. 246. 87. 38.			
OMPLA AUSE ORREC ORREC 0.00 12 4 3 1	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1	DESCRIPTION ENGINE / INSPECT NUT FLANGE M10 X 1.25 SPL THD STUD M10 X 75MM STUD M10 X 39MM GASKET TURBO MOUNTING	20.55 21.92 12.83 33.11	0. 246. 87. 38. 33.			
OMPLA AUSE ORREC [*] 0.00 12 4 3 1 1	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1 201N/1883182C1	DESCRIPTION ENGINE / INSPECT NUT FLANGE M10 X 1.25 SPL THD STUD M10 X 75MM STUD M10 X 39MM GASKET TURBO MOUNTING GASKET TURBO OUTLET	20.55 21.92 12.83 33.11 31.79	0. 246. 87. 38. 33. 31.			
DMPLA AUSE DRREC ² <u>aty</u> 0.00 12 4 3 1 1 1 1	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1 201N/1883182C1 201N/1885356C93	DESCRIPTIONENGINE / INSPECTNUT FLANGE M10 X 1.25 SPL THDSTUD M10 X 75MMSTUD M10 X 39MMGASKET TURBO MOUNTINGGASKET TURBO OUTLETTUBE ASSY LP TURBO OIL DRAIN	20.55 21.92 12.83 33.11 31.79 263.14	0. 246. 87. 38. 33. 31. 263.			
OMPLA AUSE ORREC ⁷ 0.00 12 4 3 1 1 1 1 1 1	TION ITEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1 201N/1883182C1 201N/1885356C93 201N/1885360C95	DESCRIPTIONENGINE / INSPECTNUT FLANGE M10 X 1.25 SPL THDSTUD M10 X 75MMSTUD M10 X 39MMGASKET TURBO MOUNTINGGASKET TURBO OUTLETTUBE ASSY LP TURBO OIL DRAINTUBE, ASSY HPTURBO OIL DRAIN	20.55 21.92 12.83 33.11 31.79 263.14 172.93	0. 246. 87. 38. 33. 31. 263. 172.			
OMPLA AUSE ORREC ⁷ 0.00 12 4 3 1 1 1 1 1 1 1 1	TION TEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1 201N/1883182C1 201N/1885356C93 201N/1885360C95 201N/1885590C93	DESCRIPTIONENGINE / INSPECTNUT FLANGE M10 X 1.25 SPL THDSTUD M10 X 75MMSTUD M10 X 39MMGASKET TURBO MOUNTINGGASKET TURBO OUTLETTUBE ASSY LP TURBO OIL DRAINTUBE, ASSY HPTURBO OIL DRAINTUBE ASSY, TURBO OIL SUPPLY	20.55 21.92 12.83 33.11 31.79 263.14 172.93 261.23	0. 246. 87. 38. 33. 31. 263. 172. 261.			
ОМРLA AUSE ORREC ⁷ 0.00 12 4 3 1 1 1 1 1 1 1 1 1 1 1 1	TION TEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1883181C1 201N/1883182C1 201N/1885356C93 201N/1885590C93 201N/1885590C93 201N/1885691C1	DESCRIPTIONENGINE / INSPECTNUT FLANGE M10 X 1.25 SPL THDSTUD M10 X 75MMSTUD M10 X 39MMGASKET TURBO MOUNTINGGASKET TURBO OUTLETTUBE ASSY LP TURBO OIL DRAINTUBE, ASSY HPTURBO OIL DRAINTUBE ASSY, TURBO OIL SUPPLYRING O 2.62 X 61.6 ID	20.55 21.92 12.83 33.11 31.79 263.14 172.93 261.23 3.86	0. 246. 87. 38. 33. 31. 263. 172. 261. 3.			
OMPLA AUSE ORREC ⁷ 0.00 12 4 3 1 1 1 1 1 1 1 1	TION TEM LABOR 12-10 201N/1841574C2 201N/1881555C1 201N/1882825C1 201N/1883181C1 201N/1883182C1 201N/1885356C93 201N/1885360C95 201N/1885590C93	DESCRIPTIONENGINE / INSPECTNUT FLANGE M10 X 1.25 SPL THDSTUD M10 X 75MMSTUD M10 X 39MMGASKET TURBO MOUNTINGGASKET TURBO OUTLETTUBE ASSY LP TURBO OIL DRAINTUBE, ASSY HPTURBO OIL DRAINTUBE ASSY, TURBO OIL SUPPLY	20.55 21.92 12.83 33.11 31.79 263.14 172.93 261.23	0. 246. 87. 38. 33. 31. 263. 172. 261.			



-		Estimate Operations (Cont.)		
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRIC
1	201N/5010932R91	TRBOCHGR,KIT, REMAN TURBO SUPE	3,106.28	3,106.28
1	201N/5010932R91-COI	TRBOCHGR,KIT, REMAN TURBO SUPE	300.00	300.00
JOB #11		Prepay: 0.00 Parts: \$4,747.42 Labor: \$0	Misc: \$0 Sublet: \$0	\$4,747.42
COMPLA CAUSE CORREC				
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRIC
0.00	LABOR 12-10	ENGINE / INSPECT		0.00
1	201D/FLTAC3719890	DRYER 13-16 INTERNATIONAL PROS	172.32	172.32
3	201N/1871578C1	NUT M8 X 1.25 X 10	3.04	9.12
4	201N/1875808C1	GASKET EXHAUST SINGLE LAYER	15.68	62.72
1	201N/1882684C1	SEAL EGR PIPE	42.80	42.80
1	201N/1889327C96	DUCT,KIT, EGR MIXING DUCT W/S	949.34	949.34
1	201N/1889335C95	DUCT,KIT, EGR CROSSOVER DUCT A	981.52	981.52
1	201N/2513976C92	COOLER,KIT, EGR CLR HIGH FIN D	2,934.74	2,934.74
1	201N/2513976C92-COI	COOLER,KIT, EGR CLR HIGH FIN D	500.00	500.00
1	201N/FLTACMT3903	RAPID SEAL KIT- NAVISTAR SLIM	14.00	14.00
1	201X/R134ASHOP	R134A FREON/LB	10.02	10.02
JOB #12 COMPLA CAUSE	INT CLEAN CAC	Prepay: 0.00 Parts: \$5,676.58 Labor: \$0	Misc: \$0 Sublet: \$0	\$5,676.58
CORREC	TION			
QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICI
0.00	LABOR 10-10	MISCELLANEOUS / INSPECT		0.00
		Prepay: 0.00 Parts: \$0 Labor: \$0	Misc: \$0 Sublet: \$0	\$0.00
Estimate	Operations Totals	Prepay: 0.00 Parts: \$17,213.37 Labor: \$8,486.50 Misc: \$5	8.50 Sublet: \$0.00	\$25,758.37



ESTIMATE

	compliance wit	J - parts listed were furnished in h Michigan Auto Repair Ace (P.A.300). prized Representative	<u>PLEASE REMIT PAYMEN</u> K&R Truck Sales, Inc. 840 INTERCHANGE DRI HOLLAND, MI 49423		nc. DRIVE
ALL PARTS INSTALLED ARE NEW UNLESS SPECIFICED OTHERWISE			TOTAL		\$26,258.37
RELEASED THE VEHICLE TO ME.		CONNECTION WITH THE SALE OF THIS ITEM/ITEMS.	TAX		\$0.00
EXPRESS GARAGE KEEPER'S LIEN, I HAVE NO RIGHT OF POSSESSION TO THE ABOVE VEHICLE UNTIL THE REPAIRS THERETO HAVE BEEN PAID IN FULL OR UNTIL YOU AND/OR YOUR EMPLOYEES HAVE	THE FACTORY WARRANTY CONSTITUES ALL OF THE WARRANTIES WITH RESPECT TO THE SALE OF THIS ITEM/ITEMS. THE SELLER HEREBY EXPRESSIV DISCLAIMS ALL WARRANTES ETHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN	DISP FEES		\$0.00	
TESTING AN/OR INSPECTION. AN EXPRESS GARAGE KEEPER'S LIEN IS HEREBY ACKNOWLEDGED ON THIS VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I UNDERSTAND THAT PURSUANT TO SAII		SHOP SUPPLI	ES	\$500.00	
SUPPLIER OR TRANSPORTER. I HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERAT THE VEHICLE HEREIN DESCRIBED ON THE STREEETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSE OF		SUBTOTAL	\$25,758.37	\$25,758.37	
ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE BEYOND YOUR CONTROL OR FOR ANY DELAYS CAUSE BY UNAVAILABILITY OF PARTS OR DELAY IN PARTS SHIPMENTS BY THE		PREPAY	0.00		
I HEREBY AUTHORIZE THE REPAIR WORK HERIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIALS AND AGREE THAT YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR		SUBLET	\$0.00		
TERMS: STRICTLY CASH UNLESS ARRANGEMENTS MADE		PARTS MISC	\$17,213.37 \$58.50		
FINANCE CHARGES WILL APPLY IF THE NEW BALANCE IS UNPAID ONE MONTH FROM CLOSING DATE OF STATEMENT. FINANCE CHARGE IS COMPUTED BY A PERIODIC RATE OF 2% PER MONTH WHICH IS AN ANNUAL PERCENTAGE RATE OF 24% APPLIED TO THE PREVIOUS.	DISCLAIMER	LABOR	\$8,486.50		
CUSTOMER APPROVAL FOR REPAIRS NOT COVERED BY WARRANTY, POLICY, OR FIELD CHANGES	STATEMENT OF		ESTIMATED	BILLED	

